

Engineering Safety Solutions

KiwiRail

Muri Station Risk Assessment Report

Appendix C

Condition Photographs of Muri Station



Photo1 – Looking at up platform from up platform access road



Photo 2 – Formal access to up platform



Photo 3 – Up platform looking north



Photo 4 – Up platform edge damage



Photo 5 – Up platform surface defect and montrose box



Photo 6 – Up platform platform edge defect



Photo 7 – Up platform surface defect



Photo 8 – Up platform timber to concrete platform transition



Photo 9 – Up platform timber edge condition



Photo 10 – Down platform lighting mast and damage platform edge



Photo 11 – Up platform southern end – illegal access point



Photo 12– Level crossing devoid of limit lines or TSI's



Photo 13 – Up platform northern end – misaligned transition



Photo 14 – Level crossing damage and trip hazards



Photo 15 – Level crossing surface defect



Photo 16 – Down platform – unprotected bak of platform



Photo 17 – Down platform southern end – illegal access point



Photo 18 – Down platform southern end – Platform defect



Photo 19 – Up platform southern end – illegal access point in use