## Attachment 6 to Report 00.768 Page 1 of 3

## OCTOBER 2000 FLOOD DAMAGE

## THREATS TO MASTERTON DISTRICT COUNCIL ASSETS AND UTILITIES

Location	Damage	Asset or Utility Threatened	Repairs Needed	Estimated Cost (\$)
Waipoua River				
Oxford Street – left bank	80 metres of bank erosion	Linear Park area	Willow cabling, channel alignment, and beach clearance	\$14,000
Weir No. 3 – Mawley Park	Minor damage to weir sill & ramp, some rocks washed away	Linear Park, stopbanks, & Mawley Park, Swimming Pool intake.	Collect & replace displaced rock plus 20 tonnes new rock	\$3,000
Weir No. 2 – upstream of Swing Bridge	Significant damage to weir sill & ramp, rocks washed away	Linear Park, stopbanks, sewer pipe, Swing Bridge, & SH2 Bridge	Collect up & replace displaced rock plus 100 tonnes new rock	\$7,000
Swing Bridge – left bank	Minor bank erosion	Swing bridge, stopbank, & sewer line	Trenching of willows taken from Weir No. 1 site	\$1,000
Downstream of weir No. 1 – right bank	No damage, but tree growth is putting pressure on opposite bank	Linear Park, stopbank, & sewer line	Willow removal	\$2,000
Upstream of River Road	Minor erosion	Adjoining land & River Road end	Willow trenching	\$1,000
Sub-total				\$28,000

Location Ruamahanga River 83 River Road – Watt property	Damage 100 metres of erosion	Asset or Utility Threatened	Repairs Needed	Estimated Cost (\$)
83 River Road –		Inreatened		COSE (5)
83 River Road –				Ο Ο Ο Ο Ο (Ψ)
		Watt House (only	One rock groyne,	\$24,000
wait property	downstream of	20 metres from	channel alignment, &	φ2 <b>4,</b> 000
	Waipoua River	river), another 3	willow cabling	
	confluence	houses on River	white we calling	
	••••••••	Road, and the		
		Masterton		
		Cemetery		
Masterton Cemetery	No further erosion, but	Masterton	100 tonnes of rock to	\$10,000
	groyne repairs needed	Cemetery &	repair 10 groynes, 50	
		Landfill	tonnes of linear rock	
			protection at upstream	
			end, & tree tethering	
Homebush – right	No further erosion at	Stopbank	Repair 8 groynes &	\$57,500
bank downstream of	protected u/s end, but	protecting	linear protection with	
Masterton Landfill at	groyne repairs & new	Homebush area (3	400 tonnes of rock	
Dew's &	linear rock protection	houses plus	(\$24,000)	
Blakemore's	needed.	orchards &	Repair eroded	
	Very serious erosion	glasshouse),	stopbank (\$15,000)	
	over 200 metre length	Forbes property,	stopbalik (\$15,000)	
	at d/s end including 20	and Masterton	Construct 8 new rock	
	metre stopbank breach	Oxidation Ponds	groynes with 1,200	
	metre stopeank ereach	onication ronds	tonnes of rock	
			(\$76,000)	
Forbes – right bank	Channel alignment,	Forbes property &	Willow clumps,	\$31,500
C	stopbanking, & bank	Masterton	channel maintenance,	
	protection works have	Oxidation Ponds	& gravel groyne	
	held well.		reconstruction needed	
			(\$20,000)	
	The length of old		~	
	stopbank connecting		Stopbank raising over	
	with the Oxidation		500 metre length	
Holmon loft hould	Ponds was overtopped	Holmes & Wardell	(\$25,000) 150 tonnes of rock for	¢0.400
Holmes – left bank	Groynes have worked well, 2 of the 9			\$8,400
	groynes need repair	properties, Lee Pakaraka Road, and	groyne repair, and beach clearance on	
	groynes need repair	Masterton	opposite bank	
		Oxidation Ponds	( <i>\$12,000</i> )	
Masterton Oxidation	The existing rock	Masterton	200 tonnes of rock for	\$98,000
Ponds	groynes have worked	Oxidation Ponds	groyne repair, an	φ20,000
	well, but have		additional 1,500	
	sustained significant		tonnes of rock for ten	
	damage. Also an		new groynes, and	
	additional 10 groynes		beach clearance on	
	are needed to prevent		opposite bank	
	further erosion at the			
	u/s and d/s end.			
Te Whiti	Channel realignment	Course change &	Channel realignment	\$12,600
	& overflow channel	flooding threat to	& channel block repair	
	block worked very	the Masterton to	(\$18,000)	
	well. Some repairs to	Gladstone Road,		
	channel block needed.	and to Te Whiti		
		properties		\$242,000

			Page 3 of 3	
Location	Damage	Asset or Utility Threatened	Repairs Needed	Estimated Cost (\$)
Waingawa River				
Masterton Water Supply pipeline	Bank erosion over a 200 metre length	Masterton water Supply pipeline	Channel alignment, gravel groynes, and bank battering	\$10,000
Masterton Aerodrome	Severe bank erosion over a 200 metre length has damaged end of runway	Aerodrome runway	Channel alignment, gravel groynes, rock groynes, rock protection of runway end, & reinstatement of Motorcycle Club access track	\$100,000
Sub-total				\$110,000
Total				*\$380,000

**Notes:** The estimated costs are for the work for which the 50% local share is to be funded by MDC.

The (*italic*) numbers are the total cost of the work, including the component in the Upper Ruamahanga Scheme flood damage schedule.